

Zone Report

Report Date: 22/11/2021

PERM000101 Permaconn

Zone No	Module No	Description
983	137	PERMACONN - TAMPER ALARM
981	140	PERMACONN - AUXILIARY 1
982	140	PERMACONN - AUXILIARY 2
956	300	PERMACONN - KEYPAD MONITOR / HEARTBEAT
950	301	PERMACONN - MAINS FAIL
951	302	PERMACONN - LOW BATTERY
967	306	Programming change to Permaconn Video Verification service
954	313	PERMACONN - ENGINEERING RESET
958	333	PERMACONN - MODULE FAIL
950	337	PERMACONN - EXPANSION MODULE DC LOSS
951	338	PERMACONN - EXPANSION MODULE LOW/NO BATT
953	350	PERMACONN - FAIL TO COMMUNICATE
954	351	PERMACONN - LINE FAULT TROUBLE (PM2020)
956	351	PERMACONN - LINE FAULT TROUBLE (PM1020)
955	352	PERMACONN - INTERFACE LEAD FAIL (PM2020)
956	352	PERMACONN - INTERFACE LEAD FAIL (PM1020)
956	353	PERMACONN - SERIAL LINK FAIL (RS232, RS4
967	356	Permaconn Video Verification - Offline
970	356	PERMACONN - PERMACONN POLL FAIL
970	688	Permaconn Video Verification Data usage has reached 70%
980	688	Permaconn Video Verification Data usage has reached 80%
995	688	Permaconn Video Verification Data usage has reached 95%
999	688	Permaconn Video Verification Data usage has reached 100%
967	1356	Permaconn Video Verification - Restore

