

**Type Report**

Report Date: 11/28/2019

TEPR000101 Texecom Premier 640

Type No	Description	Action Plan
121	DURESS/REMOTE FOB PANIC	Medical Alarm
130	LOCKED OUT	General Alarm
137	TAMPER	General Alarm
139	CONFIRMED ALARM	General Alarm
140	ALARM	General Alarm
150	AUXILIARY	General Alarm
220	MONITORED ALARM	General Alarm
351	ATS PATH	Low Battery
355	SUPERVISION FAULT	Low Battery
373	FIRE ZONE TAMPER	System Alert
380	MASKED/FAULT	Low Battery
383	TAMPER	System Alert
384	RF DEVICE LOW BATTERY	Low Battery
401	DISARMED	Opening (Unset), No Alarm
405	AUTOMATIC ARM DEFERRED	System Alarm
409	KEYSWITCH	Opening (Unset), No User
570	BYPASS	Zone Bypass
572	BYPASS	Zone Bypass
574	GROUP	Zone Bypass
607	WALK TEST START	System Alarm
625	DATE\TIME CHANGED	System Alarm
627	INSTALLER PROGRAMMING START	System Alarm
628	INSTALLER PROGRAMMING END	System Alarm
1121	DURESS/REMOTE FOB PANIC	Restoral, No Alarm
1137	TAMPER	Restoral, No Alarm
1139	CONFIRMED ALARM	Restoral, No Alarm
1140	RESTORE	Restoral, No Alarm
1150	AUXILIARY	Restoral, No Alarm
1220	MONITORED ALARM	Restoral, No Alarm
1321	BELL FUSE	Low Battery
1351	ATS PATH	Restoral, No Alarm
1355	SUPERVISION FAULT	Restoral, No Alarm
1373	FIRE ZONE TAMPER	Restoral, No Alarm
1380	MASKED/FAULT	Restoral, No Alarm
1383	TAMPER	Restoral, No Alarm
1384	RF DEVICE LOW BATTERY	Restoral, No Alarm

1401	ARMED	Closing (Set), No Alarm
1409	KEYSWITCH	Closing (Set), No User
1570	UN-BYPASS	Zone Bypass
1572	UN-BYPASS	Zone Bypass
1574	GROUP	Zone Bypass
1607	WALK TEST END	System Alarm