

Zone Report

Report Date: 11/28/2019

ULTR000101 Ultra Sec

Zone No	Module No	Description
998	137	TAMPER ULTRA CAPTURE BOX ULTRALINK
999	137	TAMPER ULTRALINK BOX ULTRALINK
999	301	MAINS POWER ULTRALINK
999	302	BACKUP BATTERY ULTRALINK
999	304	SOFTWARE MISMATCH ULTRALINK
995	305	UAR HAD POWER RESET ULTRALINK
999	306	PANEL ACCOUNT NUMBER CHANGED (SERIAL I/F) ULTRALINK
999	309	BACKUP BATTERY TEST ULTRALINK
998	311	PANEL TYPE MISMATCH ULTRALINK
999	311	BAD PANEL CHECKSUM ULTRALINK
999	312	MISSING PANEL HEARTBEAT TO ULTRALINK
999	313	OFF HOOK TIMEOUT PANEL TO ULTRALINK
999	314	PANEL DIAL FAIL TO ULTRALINK
64000	314	EVENT NOT DEFINED
999	316	RUNAWAY ALARMS PANEL TO ULTRALINK
64000	316	EVENT NOT DEFINED
999	317	BAD PANEL FEED TO ULTRALINK
64000	317	EVENT NOT DEFINED
901	323	ULTRALINK
902	323	ULTRALINK
903	323	ULTRALINK
904	323	ULTRALINK
905	323	ULTRALINK
906	323	ULTRALINK
907	323	ULTRALINK
908	323	-VIBRATION SENSOR ON UC-372 ENCLOSURE ULTRALINK
909	323	-VIBRATION SENSOR ON UC-351 ENCLOSURE ULTRALINK
991	350	INTERFACE POLL FAIL OVER WIRELINE (EG ADSL) ULTRALINK
992	350	INTERFACE POLL FAIL OVER WIRELESS (EG GPRS) ULTRALINK
993	350	TOTAL COMMUNICATIONS FAIL ULTRALINK
997	350	TOTAL COMMUNICATIONS FAIL ULTRALINK
998	350	GPRS INTERFACE FAIL ULTRALINK
999	350	ADSL INTERFACE FAIL ULTRALINK
999	352	BAD PACKET COUNT POSSIBLE SECURITY BREACH ULTRALINK
901	354	UAR SERIAL 1 TO AUTOMATION ULTRALINK

902	354 UAR SERIAL 2 TO AUTOMATION ULTRALINK
903	354 UAR SERIAL 3 TO AUTOMATION ULTRALINK
921	354 CAMERA INSERTED OR REMOVED ULTRALINK
922	354 CAMERA INSERTED OR REMOVED ULTRALINK
923	354 CAMERA INSERTED OR REMOVED ULTRALINK
924	354 CAMERA INSERTED OR REMOVED ULTRALINK
925	354 CAMERA INSERTED OR REMOVED ULTRALINK
926	354 CAMERA INSERTED OR REMOVED ULTRALINK
927	354 CAMERA INSERTED OR REMOVED ULTRALINK
928	354 CAMERA INSERTED OR REMOVED ULTRALINK
997	354 BSIA 175 TEST ULTRALINK
999	354 USB VIDEO CAPTURE DEVICE INSERTED OR REMOVED ULTRALINK
997	356 PANEL HAS BEEN DISCONNECTED (SERIAL I/F) ULTRALINK
999	356 PSTN NETWORK FAILURE ULTRALINK
999	627 DOWNLOAD RELAY ACTIVATED ULTRALINK
998	1137 TAMPER ULTRA CAPTURE BOX ULTRALINK
999	1137 TAMPER ULTRALINK BOX ULTRALINK
999	1301 MAINS POWER ULTRALINK
999	1302 BACKUP BATTERY ULTRALINK
999	1304 SOFTWARE MISMATCH ULTRALINK
995	1305 UAR HAD POWER RESET ULTRALINK
999	1306 PANEL ACCOUNT NUMBER CHANGED (SERIAL I/F) ULTRALINK
999	1309 BACKUP BATTERY TEST ULTRALINK
998	1311 PANEL TYPE MISMATCH ULTRALINK
999	1311 BAD PANEL CHECKSUM ULTRALINK
999	1312 MISSING PANEL HEARTBEAT TO ULTRALINK
999	1313 OFF HOOK TIMEOUT PANEL TO ULTRALINK
999	1314 PANEL DIAL FAILE TO ULTRALINK
64000	1314 EVENT NOT DEFINED
999	1316 RUNAWAY ALARMS PANEL TO ULTRALINK
64000	1316 EVENT NOT DEFINED
999	1317 BAD PANEL FEED TO ULTRALINK
64000	1317 EVENT NOT DEFINED
901	1323 ULTRALINK
902	1323 ULTRALINK
903	1323 ULTRALINK
904	1323 ULTRALINK
905	1323 ULTRALINK
906	1323 ULTRALINK
907	1323 ULTRALINK
908	1323 -VIBRATION SENSOR ON UC-372 ENCLOSURE ULTRALINK
909	1323 -VIBRATION SENSOR ON UC-351 ENCLOSURE ULTRALINK
991	1350 INTERFACE POLL FAIL OVER WIRELINE (EG ADSL) ULTRALINK
992	1350 INTERFACE POLL FAIL OVER WIRELESS (EG GPRS) ULTRALINK
993	1350 TOTAL COMMUNICATIONS FAIL ULTRALINK
997	1350 TOTAL COMMUNICATIONS FAIL ULTRALINK
998	1350 GPRS INTERFACE FAIL ULTRALINK

999	1350 ADSL INTERFACE FAIL ULTRALINK
999	1352 BAD PACKET COUNT POSSIBLE SECURITY BREACH ULTRALINK
901	1354 UAR SERIAL 1 TO AUTOMATION ULTRALINK
902	1354 UAR SERIAL 2 TO AUTOMATION ULTRALINK
903	1354 UAR SERIAL 3 TO AUTOMATION ULTRALINK
921	1354 CAMERA INSERTED OR REMOVED ULTRALINK
922	1354 CAMERA INSERTED OR REMOVED ULTRALINK
923	1354 CAMERA INSERTED OR REMOVED ULTRALINK
924	1354 CAMERA INSERTED OR REMOVED ULTRALINK
925	1354 CAMERA INSERTED OR REMOVED ULTRALINK
926	1354 CAMERA INSERTED OR REMOVED ULTRALINK
927	1354 CAMERA INSERTED OR REMOVED ULTRALINK
928	1354 CAMERA INSERTED OR REMOVED ULTRALINK
997	1354 BSIA 175 TEST ULTRALINK
999	1354 USB VIDEO CAPTURE DEVICE INSERTED OR REMOVED ULTRALINK
997	1356 PANEL HAS BEEN DISCONNECTED (SERIAL I/F) ULTRALINK
999	1356 PSTN NETWORK FAILURE ULTRALINK
999	1627 DOWNLOAD RELAY RESET ULTRALINK