

# Zone Report

Report Date: 11/28/2019

---

ULT4000101      Ultima 488

| Zone No | Module No | Description     |
|---------|-----------|-----------------|
| 45      | 100       | CODEPAD MEDICAL |
| 46      | 110       | CODEPAD FIRE    |
| 9       | 120       | -PANIC KEYFOB   |
| 10      | 120       | -PANIC KEYFOB   |
| 11      | 120       | -PANIC KEYFOB   |
| 12      | 120       | -PANIC KEYFOB   |
| 13      | 120       | -PANIC KEYFOB   |
| 14      | 120       | -PANIC KEYFOB   |
| 15      | 120       | -PANIC KEYFOB   |
| 16      | 120       | -PANIC KEYFOB   |
| 17      | 120       | -PANIC KEYFOB   |
| 18      | 120       | -PANIC KEYFOB   |
| 19      | 120       | -PANIC KEYFOB   |
| 20      | 120       | -PANIC KEYFOB   |
| 21      | 120       | -PANIC KEYFOB   |
| 22      | 120       | -PANIC KEYFOB   |
| 23      | 120       | -PANIC KEYFOB   |
| 24      | 120       | -PANIC KEYFOB   |
| 25      | 120       | -PANIC KEYFOB   |
| 26      | 120       | -PANIC KEYFOB   |
| 27      | 120       | -PANIC KEYFOB   |
| 28      | 120       | -PANIC KEYFOB   |
| 29      | 120       | -PANIC KEYFOB   |
| 30      | 120       | -PANIC KEYFOB   |
| 31      | 120       | -PANIC KEYFOB   |
| 32      | 120       | -PANIC KEYFOB   |
| 33      | 120       | -PANIC KEYFOB   |
| 34      | 120       | -PANIC KEYFOB   |
| 35      | 120       | -PANIC KEYFOB   |
| 36      | 120       | -PANIC KEYFOB   |
| 37      | 120       | -PANIC KEYFOB   |
| 38      | 120       | -PANIC KEYFOB   |
| 39      | 120       | -PANIC KEYFOB   |
| 40      | 120       | -PANIC KEYFOB   |
| 41      | 120       | CODEPAD PANIC   |

|       |                                    |
|-------|------------------------------------|
| 64000 | 121 DURESS                         |
| 0     | 300 FUSE                           |
| 30    | 301 MAINS POWER                    |
| 64000 | 307 SENSOR SELF TEST FAILURE       |
| 31    | 309 BACKUP BATTERY                 |
| 1     | 355 RF RECEIVER JAMMING            |
| 2     | 355 RF RECEIVER TAMPER SWITCH      |
| 3     | 355 RF RECEIVER FAILURE            |
| 42    | 421 CODE RETRY LIMIT EXCEEDED      |
| 44    | 602 PERIODIC TEST SIGNAL           |
| 47    | 602 TEST REPORT AFTER SIREN RESET  |
| 64000 | 607 WALK TEST                      |
| 45    | 1100 CODEPAD MEDICAL               |
| 46    | 1110 CODEPAD FIRE                  |
| 41    | 1120 CODEPAD PANIC                 |
| 64000 | 1121 DURESS                        |
| 0     | 1300 FUSE                          |
| 30    | 1301 MAINS POWER                   |
| 64000 | 1307 SENSOR SELF TEST FAILURE      |
| 31    | 1309 BACKUP BATTERY                |
| 1     | 1355 RF RECEIVER JAMMING           |
| 2     | 1355 RF RECEIVER TAMPER SWITCH     |
| 3     | 1355 RF RECEIVER FAILURE           |
| 42    | 1421 CODE RETRY LIMIT EXCEEDED     |
| 44    | 1602 PERIODIC TEST SIGNAL          |
| 47    | 1602 TEST REPORT AFTER SIREN RESET |
| 64000 | 1607 WALK TEST                     |