

Type Report

Report Date: 15/10/2020

TIANBASE01 Tiandy

Type No	Description	Action Plan
100	Motion Detected	Zone Info, No Alarm
102	Video Loss	General Alarm
103	Input Port Alarm	General Alarm
104	Output Port Alarm	General Alarm
105	Video Occlusion Alarm	General Alarm
106	Tripwire	General Alarm
107	Audio Loss	General Alarm
108	Abnormal Alarm	General Alarm
109	VCA Alarm	General Alarm