

Zone Report

Report Date: 12/08/2019

DSCA000101 DSC Alexor

Zone No	Module No	Description
0	100	KEYPAD AUXILIARY BUTTON PRESSED
0	102	A ZONE HAS FAILED ACTIVITY CHECK
0	110	KEYPAD FIRE BUTTON PRESSED
0	120	KEYPAD PANIC BUTTON PRESSED
0	121	KEYPAD DURESS CODE ENTERED
0	139	CROSS ZONE ALARM - 2 ZONES
0	145	TAMPER GENERAL CASE/COVER
0	300	AN RF JAM OR HARDWARE FAULT HAS OCCURRED
1	300	RADIO/SIM-GSM-ETHERNET-SMS CONFIG
0	301	MAINS POWER
0	302	BACKUP BATTERY
0	312	AUX CURRENT DRAW EXCEEDS 200MA
0	330	DETECTED AN ALTERNATE COMMUNICATOR FAULT
1	350	RECEIVER 1 ABSENT OR FAILED TO INITIALISE
2	350	RECEIVER 2 ABSENT OR FAILED TO INITIALISE
3	350	RECEIVER 3 ABSENT OR FAILED TO INITIALISE
4	350	RECEIVER 4 ABSENT OR FAILED TO INITIALISE
0	351	LINE CURRENT NOT AVAILABLE ON THE PHONE LINE
0	373	FIRE ZONE
0	378	2ND CROSS ZONE ALARM HAS NOT OCCURED
70	380	WIRELESS SUPERVISION FAULT KEYPAD 1
71	380	WIRELESS SUPERVISION FAULT KEYPAD 2
72	380	WIRELESS SUPERVISION FAULT KEYPAD 3
73	380	WIRELESS SUPERVISION FAULT KEYPAD 4
80	380	WIRELESS SUPERVISION FAULT SIREN 1
81	380	WIRELESS SUPERVISION FAULT SIREN 2
82	380	WIRELESS SUPERVISION FAULT SIREN 3
83	380	WIRELESS SUPERVISION FAULT SIREN 4
70	383	TAMPER KEYPAD 1
71	383	TAMPER KEYPAD 2
72	383	TAMPER KEYPAD 3
73	383	TAMPER KEYPAD 4
80	383	TAMPER SIREN 1
81	383	TAMPER SIREN 2
82	383	TAMPER SIREN 3

83	383 TAMPER SIREN 4
0	384 WIRELESS KEY-PROX DEVICE-KEYPAD OR SIREN LOW BATTERY
70	384 KEYPAD 1 LOW BATTERY
71	384 KEYPAD 2 LOW BATTERY
72	384 KEYPAD 3 LOW BATTERY
73	384 KEYPAD 4 LOW BATTERY
80	384 SIREN 1 LOW BATTERY
81	384 SIREN 2 LOW BATTERY
82	384 SIREN 3 LOW BATTERY
83	384 SIREN 4 LOW BATTERY
0	400 OTHER THAN BY USER CODE
40	400 MASTER CODE
40	401 MASTER CODE
40	406 MASTER CODE. CANCEL
0	411 A DOWNLOAD SESSION STARTED
0	412 A DOWNLOAD SESSION TERMINATED
0	453 LATE TO DISARM
0	458 DISARM AFTER AN ALARM
40	458 MASTER CODE. DISARM AFTER AN ALARM
40	459 [MASTER CODE. RECENT ARMING. ALARM OCCURED WITHIN 2 MINS OF]
0	461 TOO MANY WRONG KEYPAD PRESSES
0	601 MANUALLY TRIGGERED TEST SIGNAL
0	602 PERIODIC TEST SIGNAL
40	607 MASTER CODE. WALK TEST STARTED
0	627 CONNECTED TO PROGRAMMING SOFTWARE/INSTALLER MODE ENTERED
0	628 DISCONNECTED FROM PROGRAMMING SOFTWARE/INSTALLER MODE EXITED
0	654 NO ZONE ACTIVITY OR ARMING DETECTED
0	1100 KEYPAD AUXILIARY BUTTON PRESSED
0	1102 A ZONE HAS FAILED ACTIVITY CHECK
0	1110 KEYPAD FIRE BUTTON PRESSED
0	1120 KEYPAD PANIC BUTTON PRESSED
0	1121 KEYPAD DURESS CODE ENTERED
0	1145 TAMPER GENERAL CASE/COVER
0	1300 AN RF JAM OR HARDWARE FAULT HAS OCCURRED
1	1300 RADIO/SIM-GSM-ETHERNET-SMS CONFIG
0	1301 MAINS POWER
0	1302 BACKUP BATTERY
0	1305 POWERED UP WHEN MAINS POWER RESTORED
0	1312 AUX CURRENT DRAW EXCEEDS 200MA
0	1330 DETECTED AN ALTERNATE COMMUNICATOR FAULT
1	1350 RECEIVER 1 ABSENT OR FAILED TO INITIALISE
2	1350 RECEIVER 2 ABSENT OR FAILED TO INITIALISE
3	1350 RECEIVER 3 ABSENT OR FAILED TO INITIALISE
4	1350 RECEIVER 4 ABSENT OR FAILED TO INITIALISE
0	1351 LINE CURRENT NOT AVAILABLE ON THE PHONE LINE
0	1354 RESTORED COMMS VIA PH1 TO 4 (AFTER FAIL TO COMMUNICATE)

0	1373 FIRE ZONE
70	1380 WIRELESS SUPERVISION FAULT KEYPAD 1
71	1380 WIRELESS SUPERVISION FAULT KEYPAD 2
72	1380 WIRELESS SUPERVISION FAULT KEYPAD 3
73	1380 WIRELESS SUPERVISION FAULT KEYPAD 4
80	1380 WIRELESS SUPERVISION FAULT SIREN 1
81	1380 WIRELESS SUPERVISION FAULT SIREN 2
82	1380 WIRELESS SUPERVISION FAULT SIREN 3
83	1380 WIRELESS SUPERVISION FAULT SIREN 4
70	1383 TAMPER KEYPAD 1
71	1383 TAMPER KEYPAD 2
72	1383 TAMPER KEYPAD 3
73	1383 TAMPER KEYPAD 4
80	1383 TAMPER SIREN 1
81	1383 TAMPER SIREN 2
82	1383 TAMPER SIREN 3
83	1383 TAMPER SIREN 4
0	1384 WIRELESS KEY-PROX DEVICE-KEYPAD OR SIREN LOW BATTERY
70	1384 KEYPAD 1 LOW BATTERY
71	1384 KEYPAD 2 LOW BATTERY
72	1384 KEYPAD 3 LOW BATTERY
73	1384 KEYPAD 4 LOW BATTERY
80	1384 SIREN 1 LOW BATTERY
81	1384 SIREN 2 LOW BATTERY
82	1384 SIREN 3 LOW BATTERY
83	1384 SIREN 4 LOW BATTERY
0	1400 OTHER THAN BY USER CODE
40	1400 MASTER CODE
40	1401 MASTER CODE
0	1456 PARTIAL-ONE OR MORE ZONES BYPASSED
40	1456 MASTER CODE. PARTIAL. ONE OR MORE ZONES BYPASSED
0	1461 TOO MANY WRONG KEYPAD PRESSES
40	1607 MASTER CODE. WALK TEST FINISHED

