

Type Report

Report Date: 11/28/2019

U888000101 Ultima 844/862/880

| Type No | Description | Action Plan |
|---------|--------------------------|---------------------------|
| 100 | MEDICAL | Medical Alarm |
| 110 | FIRE | Medical Alarm |
| 120 | PANIC | Medical Alarm |
| 121 | DURESS | Medical Alarm |
| 122 | HOLDUP | Medical Alarm |
| 130 | ALARM | General Alarm |
| 133 | 24HR BURGLARY | General Alarm |
| 137 | TAMPER | Low Battery |
| 144 | TAMPER | System Alert |
| 307 | SENSOR SELF TEST FAILURE | System Alarm |
| 380 | TROUBLE | Low Battery |
| 384 | RF LOW BATTERY | System Alarm |
| 402 | DISARMED | Opening (Unset), No Alarm |
| 456 | PARTIAL | Opening (Unset), No Alarm |
| 571 | FIRE | Zone Bypass |
| 572 | 24HR | Zone Bypass |
| 573 | BYPASS | Zone Bypass |
| 607 | WALK TEST | System Alarm |
| 1100 | MEDICAL | Restoral, No Alarm |
| 1110 | FIRE | Restoral, No Alarm |
| 1120 | PANIC | Restoral, No Alarm |
| 1121 | DURESS | Restoral, No Alarm |
| 1122 | HOLDUP | Restoral, No Alarm |
| 1130 | RESTORE | Restoral, No Alarm |
| 1133 | 24HR BURGLARY | Restoral, No Alarm |
| 1137 | TAMPER | Restoral, No Alarm |
| 1144 | TAMPER | Restoral, No Alarm |
| 1307 | SENSOR SELF TEST FAILURE | Restoral, No Alarm |
| 1380 | RESTORE | Restoral, No Alarm |
| 1384 | RF LOW BATTERY | Restoral, No Alarm |
| 1402 | ARMED | Closing (Set), No Alarm |
| 1456 | PARTIAL | Closing (Set), No Alarm |
| 1571 | FIRE | Zone Bypass |
| 1572 | 24HR | Zone Bypass |
| 1573 | UN-BYPASS | Zone Bypass |
| 1607 | WALK TEST | Restoral, No Alarm |

